

Sanitary Sewer Overflow 5-Day Follow Up Report

Division of Surface Water

Report Submitted By	
Date:	4/6/2016
Facility name:	Gary L. Kron WRF
Ohio NPDES permit no.:	3PK00033*MD
Period covered by report:	4/5/2016
Contact person	
Name:	Michael McGlothin
Title:	Superintendent
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio 44060
County:	Lake
Telephone:	(440)350 - 3431
Email:	Michael.mcglothin@lakecountyohio.gov
Signature required at end of form	
Overflow Information	
Event start date and time — if multiple locations, include information for each	4/5/2016 at 11:10am
Event end date and time	4/5/2016 at12:00pm
Location(s) the SSO — include unique ID number of one exists	Williams Lift Station force main air release valve No. 405
Destination(s) of overflow	☐ Basement or building ☑ Ground ☐ Storm sewer to receiving water ☐ Directly to receiving water
Estimated volume (million gallons) - if multiple locations, include volume for each	0.00025 MGD
Sewer system component(s) from which release occurred	☐ Manhole ☐ Constructed overflow ☐ Pipe crack ☐ Pump station ☐ Other (explain) Air release valve on force main
Cause(s) of overflow	☐ Extreme weather ☐ Equipment failure ☐ Power failure ☐ Debris in line ☐ Roots ☐ Grease ☐ Other blockages ☐ Line deterioration ☐ Vandalism ☐ Other (explain)